

# Product Change Notification

Raychem Circuit Protection Products

**Type of Notification:** Obsolescence / End of Life of *GTCx26-XXXX- P0X, GTCx28-XXXX- P05, GTCx28-XXXX- P15, GTCA28-XXXX-P0X, GTCx36-XXXX-P0X/FS, GTCx37-XXXX-P10/FS, GTCx38-XXXX-PXX/FS, GTCx38-XXXX-Q10/FS* devices.

Issue Date	Notification No.
February 24, 2009	TEPC2009-006

**Description of Change:**  
 This letter is to notify our customers that Tyco Electronics will be discontinuing the *GTCx26-XXXX- P0X, GTCx28-XXXX- P05, GTCx28-XXXX- P15, GTCA28-XXXX-P0X, GTCx36-XXXX-P0X/FS, GTCx37-XXXX P10/FS, GTCx38-XXXX-PXX/FS, GTCx38-XXXX-Q10/FS* devices.

**Products Affected:**  
 Please refer to attached list.

**Additional Information**

Customers are requested to provide confirmation of EOL of those affected by May 15, 2009. Ordering details of these devices are as follow:

Confirmation of EOL	May 15, 2009
Final date of placing purchase orders (PO)	July, 31 2009
Last delivery date	December 31, 2009

\* Effective now all orders placed will be NCNR.

Please note:  
 Our *GTCS23-XXXM-R01, GTCX25-XXXM-R02, GTCX26-XXXM-R05, GTCX28-XXXM-R10/R20, GTCX35-XXXM-R05, GTCX36-XXXM-R10, GTCX37-XXXM-R10, GTCX38-XXXM-R10* are available and are not affected by this notification.

<b>Author:</b>	Weiqing Guo	<b>Date:</b>	February 24, 2009
<b>Job Title:</b>	Global Product Manager		

## Product Change Notification

Raychem Circuit Protection Products

**Type of Notification:** Obsolescence / End of Life of *GTCx26-XXXX- P0X, GTCx28-XXXX- P05, GTCx28-XXXX- P15, GTCA28-XXXX-P0X, GTCx36-XXXX-P0X/FS, GTCx37-XXXX-P10/FS, GTCx38-XXXX-PXX/FS, GTCx38-XXXX-Q10/FS* devices.

Issue Date	Notification No.
February 24, 2009	TEPC2009-006

### Products Affected and Replacement Parts:

<b>Products Affected</b>	<b>Replacement Parts</b>
<b>GTCx26-xxxM-Pxx</b>	<b>GTCx26-xxxM-Rxx</b>
GTCN26-101M-P02-B	GTCN26-101M-R05
GTCN26-101M-P02	GTCN26-101M-R05
GTCN26-231M-P05-B	GTCN26-231M-R05
GTCN26-231M-P05	GTCN26-231M-R05
GTCN26-351M-P05-B	GTCN26-351M-R05
GTCN26-351M-P02	GTCN26-351M-R05
<b>GTCx28-xxxx-Pxx</b>	<b>GTCx28-xxxM-Rxx</b>
GTCN28-750M-P05	GTCN28-750M-R05
GTCA28-750M-P05	GTCA28-750M-R05
GTCN28-900M-P05	GTCN28-900M-R05
GTCA28-900M-P05	GTCA28-900M-R05
GTCN28-151M-P05	GTCN28-151M-R05
GTCA28-151M-P05	GTCA28-151M-R05
GTCN28-231L-P05	GTCN28-231M-R05
GTCA28-231L-P05	GTCA28-231M-R05
GTCN28-251L-P05	GTCN28-251M-R05
GTCA28-251L-P05	GTCA28-251M-R05
GTCN28-301L-P05	GTCN28-301M-R05
GTCA28-301L-P05	GTCA28-301M-R05
GTCN28-351L-P05	GTCN28-351M-R05
GTCA28-351L-P05	GTCA28-351M-R05
GTCN28-401L-P05	GTCN28-401M-R05
GTCA28-401L-P05	GTCA28-401M-R05
GTCN28-471L-P05	GTCN28-471M-R05
GTCA28-471L-P05	GTCA28-471M-R05
GTCN28-601L-P05	GTCN28-601M-R05
GTCA28-601L-P05	GTCA28-601M-R05
GTCN28-801L-P05	TBD
GTCA28-801L-P05	TBD

<b>Products Affected</b>	<b>Replacement Parts</b>
<b>GTCx28-xxxM-Pxx</b>	<b>GTCx28-xxxM-Rxx</b>
GTCN28-900M-P15	GTCN28-900M-R20
GTCA28-900M-P15	GTCA28-900M-R20
GTCN28-151M-P15	GTCN28-151M-R20
GTCA28-151M-P15	GTCA28-151M-R20
GTCN28-231M-P15	GTCN28-231M-R20
GTCA28-231M-P15	GTCA28-231M-R20
GTCN28-251M-P15	TBD
GTCA28-251M-P15	TBD
GTCN28-351M-P15	TBD
GTCA28-351M-P15	TBD
<b>GTCx28-xxxx-Pxx</b>	<b>GTCx28-xxxM-Rxx</b>
GTCA28-102M-P03	TBD
GTCA28-152L-P03	TBD
GTCA28-212M-P03	TBD
GTCA28-242M-P03	TBD
GTCA28-272L-P03	TBD
GTCA28-302M-P01	TBD
GTCA28-312L-P03	TBD
GTCA28-402M-P01	TBD
<b>GTCx36-xxxM-Pxx</b>	<b>GTCx36-xxxM-Rxx</b>
GTCN36-900M-P05	GTCN36-900M-R10
GTCR36-900M-P05	GTCR36-900M-R10
GTCR36-900M-P05-FS	GTCR36-900M-R10-FS
GTCN36-231M-P10	GTCN36-231M-R10
GTCR36-231M-P05	GTCR36-231M-R10
GTCR36-231M-P05-FS	GTCR36-231M-R10-FS
GTCN36-351M-P05	GTCN36-351M-R10
GTCR36-351M-P05	GTCR36-351M-R10
GTCR36-351M-P05-FS	GTCR36-351M-R10-FS

## Product Change Notification

Raychem Circuit Protection Products

**Type of Notification:** Obsolescence / End of Life of *GTCx26-XXXX- P0X, GTCx28-XXXX- P05, GTCx28-XXXX- P15, GTCA28-XXXX-P0X, GTCx36-XXXX-P0X/FS, GTCx37-XXXX-P10/FS, GTCx38-XXXX-PXX/FS, GTCx38-XXXX-Q10/FS* devices.

Issue Date	Notification No.
February 24, 2009	TEPC2009-006

### Products Affected and Replacement Parts:

Products Affected	Replacement Parts
<b>GTCx37-xxxM-Pxx</b>	<b>GTCx37-xxxM-Rxx</b>
GTCR37-900M-P10	GTCR37-900M-R10
GTCR37-900M-P10-FS	GTCR37-900M-R10-FS2
GTCT37-900M-P10-FS	TBD
GTCR37-151M-P10	GTCR37-151M-R10
GTCR37-151M-P10-FS	GTCR37-151M-R10-FS2
GTCT37-151M-P10-FS	TBD
GTCR37-201M-P10	GTCR37-201M-R10
GTCR37-201M-P10-FS	GTCR37-201M-R10-FS2
GTCT37-201M-P10-FS	TBD
GTCR37-231M-P10	GTCR37-231M-R10
GTCR37-231M-P10-FS	GTCR37-231M-R10-FS2
GTCT37-231M-P10-FS	TBD
GTCR37-251M-P10	GTCR37-251M-R10
GTCR37-251M-P10-FS	GTCR37-251M-R10-FS2
GTCT37-251M-P10-FS	TBD
GTCR37-261M-P10	GTCR37-261M-R10
GTCR37-261M-P10-FS	GTCR37-261M-R10-FS2
GTCT37-261M-P10-FS	TBD
GTCR37-301M-P10	GTCR37-301M-R10
GTCR37-301M-P10-FS	GTCR37-301M-R10-FS2
GTCT37-301M-P10-FS	TBD
GTCR37-351M-P10	GTCR37-351M-R10
GTCR37-351M-P10-FS	GTCR37-351M-R10-FS2
GTCT37-351M-P10-FS	TBD
GTCR37-401M-P10	GTCR37-401M-R10
GTCR37-401M-P10-FS	GTCR37-401M-R10-FS2
GTCT37-401M-P10-FS	TBD
GTCR37-551M-P10	GTCR37-551M-R10
GTCR37-551M-P10-FS	GTCR37-551M-R10-FS2
GTCT37-551M-P10-FS	TBD

Products Affected	Replacement Parts
<b>GTCx38-xxxM-Qxx</b>	<b>GTCx38-xxxM-Rxx</b>
GTCN38-900M-Q10	GTCN38-900M-R10
GTCN38-900M-Q10-FS	GTCN38-900M-R10-FS
GTCR38-900M-Q10	GTCR38-900M-R10
GTCR38-900M-Q10-FS	GTCR38-900M-R10-FS
GTCN38-151M-Q10	GTCN38-151M-R10
GTCN38-151M-Q10-FS	GTCN38-151M-R10-FS
GTCR38-151M-Q10	GTCR38-151M-R10
GTCR38-151M-Q10-FS	GTCR38-151M-R10-FS
GTCN38-231M-Q10	GTCN38-231M-R10
GTCN38-231M-Q10-FS	GTCN38-231M-R10-FS
GTCR38-231M-Q10	GTCR38-231M-R10
GTCR38-231M-Q10-FS	GTCR38-231M-R10-FS
GTCN38-251M-Q10	GTCN38-251M-R10
GTCN38-251M-Q10-FS	GTCN38-251M-R10-FS
GTCR38-251M-Q10	GTCR38-251M-R10
GTCR38-251M-Q10-FS	GTCR38-251M-R10-FS
GTCN38-351M-Q10	GTCN38-351M-R10
GTCN38-351M-Q10-FS	GTCN38-351M-R10-FS
GTCR38-351M-Q10	GTCR38-351M-R10
GTCR38-351M-Q10-FS	GTCR38-351M-R10-FS
GTCN38-421M-Q10	GTCN38-421M-R10
GTCN38-421M-Q10-FS	GTCN38-421M-R10-FS
GTCR38-421M-Q10	GTCR38-421M-R10
GTCR38-421M-Q10-FS	GTCR38-421M-R10-FS
GTCN38-501M-Q10	GTCN38-501M-R10
GTCN38-501M-Q10-FS	GTCN38-501M-R10-FS
GTCR38-501M-Q10	GTCR38-501M-R10
GTCR38-501M-Q10-FS	GTCR38-501M-R10-FS

## Product Change Notification

Raychem Circuit Protection Products

**Type of Notification:** Obsolescence / End of Life of *GTCx26-XXXX- P0X, GTCx28-XXXX- P05, GTCx28-XXXX- P15, GTCA28-XXXX-P0X, GTCx36-XXXX-P0X/FS, GTCx37-XXXX-P10/FS, GTCx38-XXXX-PXX/FS, GTCx38-XXXX-Q10/FS* devices.

Issue Date	Notification No.
February 24, 2009	TEPC2009-006

### Products Affected and Replacement Parts:

<i><b>Products Affected</b></i>	<i><b>Replacement Parts</b></i>
<b>GTCx38-xxxM-Pxx</b>	<b>GTCx38-xxxM-Rxx</b>
GTCR38-231M-P10-FS	GTCR38-231M-R10-FS2
GTCR38-251M-P10-FS	GTCR38-251M-R10-FS2
GTCN38-351M-P20	TBD
GTCN38-351M-P20-FS	TBD
GTCR38-351M-P20	TBD
GTCR38-351M-P20-FS	TBD